




Suspect aluminum rib is located inside engine compartment at this location (A36)



External Power Supply Connection Box

View looking toward firewall. Heater Hose has been removed for this photo

Heater Hose

Corrosion location